

Oil Field Environmental Incident Summary

Incident: 20160607142545 **Date/Time of Notice:** 06/07/2016 14:25

Responsible Party: Oneok Rockies Midstream

Well Operator: ONEOK ROCKIES MIDSTREAM

Well Name: Grasslands Plant

Field Name:

Well File #:

Date Incident: 6/7/2016

Time Incident: 07:00

Facility ID Number:

County: MCKENZIE

Twp: 148

Rng: 105

Sec: 36

Qtr: SE

Location Description: 16001 Bennie Peer Road
Sidney, MT 59270

Submitted By: Levi Weltikol

Received By:

Contact Person: Levi Weltikol
896 25th St SE
Sidney, MT 59270

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Equipment Failure

Release Contained in Dike: Yes - On Facility Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine						
Other	5	Gallons				

Description of Other Released Contaminant:

Amine

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

No immediate risk

Areal Extent:

Potential Environmental Impacts:

No immediate environmental impacts

Action Taken or Planned:

Leak stopped before operator found contaminate. Will monitor closely for any further leaks

Wastes Disposal Location: Certified landfill

Agencies Involved:

Updates

Date: 6/9/2016 **Status:** Awaiting Documentation

Author: Souder, Taylor

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Spoke with OneOK and asked if we could receive pictures on the clean up process. Waiting on those photos.